
City of Baltimore Wet Smoke and Dyed	Page 1 of 1	
Sewershed: Gwynns Falls	Company: Savin	Date: 4/22/2009
Test to be performed: Smoke Dyed Water X	Ground Condition: Dry ✓ Damp ☐ Wet ☐	Supervisor: JAW
Manhole_ID: S01AA1013MH	Test ID: <u>D1032-026012</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
		Start of Survey	
		Manhole	S01AA1013MH
		Water Level	
12		Infil Runner	@ jt, dye not visible
		Dye Test Visible	@ IR, 0.5gpm
		Dye Test Visible	@ IR, <0.1 gpm
		Dye Test Visible	@ IG, 3gpm
		Dye Test Visible	@ IG, 7gpm
11		Tap Factory Active	
		Abandoned Survey	DYE FLOOD COMPLETED
	12	12	Start of Survey Manhole Water Level 12 Infil Runner Dye Test Visible Tap Factory Active